

DETECTASMOKE®

TECHNICAL BULLETIN

No 2025002

DetectaSmoke® Smoke Test Aerosol operational reminder

Due to its Ultra Low formula, DetectaSmoke® only needs a 1 second burst to activate alarms!

Spraying longer than this is unnecessary and wastes gas.

Excessive spraying can create a normal freezing effect created when discharging aerosols which could freeze the moisture in the air creating ice to form on the DetectaHead® which will melt and produce water which might be considered as excessive aerosol content.

There is no oil in DetectaSmoke®. Ice/Water created by excessive spraying will eventually evaporate but by only using a 1 second spray this should avoid the issue.

John Stones
Technical Support



Scan QR code to view technical
bulletin video or visit:
youtu.be/UiaIWDobT14

